

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LL1571  
ENE  
> 1  
1.990 mi.  
10506 ft.

**SPILL NUMBER 0305268**  
**2612 AVE Z 1ST FLOOR**  
**BROOKLYN, NY**

**NY Spills S106017245**  
**N/A**

Site 2 of 2 in cluster LL

Relative:  
Higher

Actual:  
10 ft.

SPILLS:

Name: SPILL NUMBER 0305268  
Address: 2612 AVE Z 1ST FLOOR  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0305268 / 2003-12-15  
Facility ID: 0305268  
Facility Type: ER  
DER Facility ID: 181321  
Site ID: 219265  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2003-08-01  
Investigator: CESA WYER  
Referred To: Not reported  
Reported to Dept: 2003-08-18  
CID: 281  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2003-08-18  
Spill Record Last Update: 2003-12-15  
Spiller Name: Not reported  
  
Spiller Company: DYKER ASSOCIATES  
Spiller Address: UNKNOWN  
Spiller Company: 001  
Contact Name: RADISLAV TISNOVSKY  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was SAWYER 8/18/03 DDO Sawyer talked to Mr. Tisnovsky and he explained he was in the process of having the area tested and remediated. He has already retained a lawyer and plans to persue the builder (Dyker Assocites). His cell phone number is (718) 490-1313. 8/25/03 1323 Hrs - Sawyer - Talked to Jim Mulvey (Allstate's Environmental Consultant) who notified me that today soil and air samples were taken to be analyzed. His number is (516) 322-4543. 12/15/03 1319 Hrs - Sawyer - Reviewed the report and sampling results forwarded by Milro, and received December 4, 2003. Judging from the information presented in the report, there is no further action needed. Closed."

Remarks: "Caller purchased above property on 1/2002 and noticed stain. Caller states he brought this to builders attention and was told it was no problem. Room was carpeted covered stain. Caller states odor became unbearable approx 2 weeks ago and he removed carpet to find stain still there. Caller is requesting to speak to DEC."

All Materials:

Site ID: 219265  
Operable Unit ID: 871938

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit: 01  
Material ID: 502527  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported